## **Technical Data Sheet**

## **Sub-X® Mounting Medium**

## #13519

A permanent mounting medium formulated for use with Sub-X® Clearing Agent but may be used for all routine mounting. DO NOT USE Sub-X® clearant to dilute mounting medium. A small amount of Toluene or Xylene must be used to reduce viscosity. Xylene or toluene must be used to remove coverslips that have set up.

Store at room temperature 59-86°F(15-30°C)

Flash point CC: 53°F (12°C)

Hazardous Ingredient	% wt.	CAS no.
Toluene	<75	108-88-3
Acrylic Resin	<50	80-62-6
Butyl Benzyl Phthalate	<10	85-68-7
Antioxidant	<1	128-37-0